

# SELDER & COMPANY AB

## WORK MANUAL FOR STRONG SOFT SOAP

[www.selder.com](http://www.selder.com)

23.3.2021



**Very tough dirt/grime; engines, etc.:** brush the surface with STRONG SOFT SOAP and let it sit for a while. Use a dish brush on the dirt/grime. Rinse off with water once the dirt/grime has dissolved. Repeat if necessary.

**Tough dirt/grime:** dilute STRONG SOFT SOAP to 50 % with water or until it can be sprayed using a hand-held sprayer. Spray generously on the dirty surface and let sit for a few minutes. Remove the dirt and grime, then rinse off.

**Light dirt/grime:** dilute the STRONG SOFT SOAP to 1/100 and apply. Let sit for a while and scrub with a brush or rinse off using a pressure washer.

**Brushes with linseed oil or linseed oil paint on them:** cover the brush with STRONG SOFT SOAP and knead it. The soft soap thins and/or is tinted. Rinse with water. Then squeeze the water from the brush and cover once more with soft soap. Repeat until the soap no longer thins and/or is tinted.

Let the brush dry thoroughly before using it again with Selder & Co's paints or oils.

**Dried linseed oil or linseed oil paint leftovers:** soak the workpiece in undiluted STRONG SOFT SOAP until the dirt has softened and can be removed. This may take several days.

**Note:** STRONG SOFT SOAP dissolves linseed oil paints and attacks aluminum.

### WORKER SAFETY

Use gloves when working with STRONG SOFT SOAP, as it dries out the skin. Mind your eyes, as STRONG SOFT SOAP is a potent irritant.